

Fig. 3


[illegible]

Fig. 4









Fig. 5b



Technical drawing of a mechanical assembly. The drawing shows a cross-section of a component (16) with a central hole. A bolt (160) is shown passing through the component. A nut (150) is shown on the bolt. A washer (148) is shown between the nut and the component. A flange (604) is shown at the bottom of the component.

Fig. 5d










Fig. 1a






Fig. 8a







Fig. 8b






FIG. 9a




FIG. 9b

1003750 434 1003750




Fig. 10








FIG. 13

